Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Operator: PEOPLES GAS LIGHT AND COKE CO.	Operator ID#: 15329
Inspection Date(s): 5/5/2015, 5/6/2015, 5/7/2015, 5/8/2015	Man Days: 4
Inspection Unit: North Shop	
Location of Audit: Chicago	
Exit Meeting Contact: Derek Leggitt	
Inspection Type: Design Testing and Construction	
Pipeline Safety Representative(s): Aaron McElravy	
Company Representative to Receive Report: Amy Kenny, Tom Webb	
Company Representative's Email Address: ALKenny@peoplesgasdelivery.com, TJWebb@peoples	sgasdelivery.com

CONSTRUCTION INFORMATION			
Location of Construction:		Construction P	erformed By:
4106 Mason between W. Irving Park Road	and W. Berteau Avenue.	Michels Corpora	tion (PGL Contractor)
Contractor Foreman:	Wes Newholm	•	
Operator Inspector:	Matt Strange (EN Engineering)		
	Person(s) On J	ob Site	
Harold Cunningham	Jim Kerr	1	Wes Newholm
Description of Construction:			

Installation of 1 inch service from 2 inch main to the riser location.

SERVICE INSTALLATION		Status
[192.55]	Steel	No
[192.59]	PE	Yes
[192.59]	Other	No
[192.619,192.621,192.623]	MAOP	25psig
[192.5]	Class location :	Class 4
[192.53]	Are components qualified for use?	Satisfactory
[192.63(a)(2)]	Pipe Size :	1 inch CTS

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

192.55,192.59]		
	Manufacturer :	DriscoPlex 6500
192.55,192.59]	Pipe Grade :	D2513
[92.55,192.59]	Wall Thickness :	.099
[92.63]	Are pipe, valves, and fittings properly marked for identification?	Satisfactory
eneral Comment:		
Il fittings and pipe observed contained the required	markings.	
[92.227]	Welder qualification date:	Not Applicable
eneral Comment:		
he construction activities observed did not contain	welding of steel pipe.	
[92.227]	Welder's Name:	Not Applicable
eneral Comment:		
he construction activities observed did not contain	welding of steel pipe.	
192.225,192.275,192.277,192.279,192.20	Is pipe joined in accordance with approved written procedures?	Satisfactory
[92.285]	Date of Qualification :	6-12-14
[92.285]	Joiner's name:	Jim Kern
[92.455]	Is buried metallic pipe coated?	Not Applicable
eneral Comment:		
he audit included the installation of PE pipe, no ste	el pipe or fittings were observed during this inspection.	
192.455(a)(1)]	Is cathodic protection being provided?	Not Applicable
eneral Comment:		
he audit included the installation of PE pipe, no ste	el pipe or fittings were observed during this inspection.	
192.455(a)(1)]	Is cathodic protection being provided? By Anodes:	No
eneral Comment:		
he audit included the installation of PE pipe, no ste	el pipe or fittings were observed during this inspection.	
192.455(a)(1)]	Is cathodic protection being provided? By Rectifier:	No
eneral Comment:	•	
he audit included the installation of PE pipe, no ste	el pipe or fittings were observed during this inspection.	
192.461]	Does coating meet 192.461?	Not Applicable
eneral Comment:	•	
he audit included the installation of PE pipe, no ste	el pipe or fittings were observed during this inspection.	

PEOPLES GAS LIGHT AND COKE CO./5-8-2015

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.461(c)]	Is coating inspected just prior to being installed in the ditch?	Not Applicable
General Comment:		
The audit included the installation of PE pipe,	no steel pipe or fittings were observed during this inspection.	
[192.479]	Are above ground facilities cleaned and coated or jacketed as needed?	Satisfactory
General Comment:		
The riser and above ground piping was coated	d and protected from atmospheric corrosion.	
[192.467]	Are pipelines electrically isolated from other underground metallic structures?	Not Applicable
General Comment:		
The audit included the installation of PE pipe,	no steel pipe or fittings were observed during this inspection.	
[192.319]	Is ditch back-filled to provide firm support and prevent damage to pipe or coating?	Satisfactory
[192.321(c)]	Is plastic pipe installed as to minimize shear and tensile forces?	Satisfactory
[192.321]	Does plastic pipe have means of locating while underground?	Satisfactory
[192.325]	Are required clearances from underground structures being maintained?	Satisfactory
[192.327(a)]	Is required cover being obtained for the service line?	Satisfactory
[192.503]	Are general testing requirements being met?	Satisfactory
General Comment:		
Staff observed a pressure test of the service l	ine located at 4106 Mason Avenue.	
[192.517]	Are records being made of strength and leak tests?	Satisfactory
General Comment:		
Staff observed a pressure test of the service l	ine located at 4106 Mason Avenue.	
[192.807]	Were covered employees Operator Qualification records reviewed to ensure qualification?	Satisfactory
[192.805(c)]	Were non-qualified personnel being directed and observed by a qualified individual?	Not Applicable
General Comment:	· · · · · · · · · · · · · · · · · · ·	
All personnel were qualified in the task they w	ere performing.	
[192.805(c)]	Were span of control limitations being followed?	Not Applicable
General Comment:	· · · · · · · · · · · · · · · · · · ·	
All personnel were qualified in the task they w	ere performing.	
Was a Protocol 9 (Form 15) Complet	ted?	No

PEOPLES GAS LIGHT AND COKE CO./5-8-2015

Page 3 of 5

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

General Comment:		
Staff did not complete PHMSA Form	n 15 during this audit.	
[192.614]	Were One Call Notifications performed as required?	Satisfactory
[192.614]	Dig Ticket #	#56144197
[192.383(b)]	Is an EFV installed on any new or replaced service line serving a single-family residence?	Satisfactory
[192.751]	Are adequate steps taken to minimize the potential for accidental ignition?	Satisfactory

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.